

# raccords E4/S4

type socket-welding 2 côtés

Désignation	A × B	C	D	E	F	G
ABF SSW 1/0	2 × 4	14	14	34	4	6
ABF SSW 1/1P	4 × 6	22	22	52	6	10
ABF SSW 1/1	6 × 10	24	25	58	7	13
ABF SSW 1/2	8 × 13	29	29	62	7	17
ABF SSW 1/3	12 × 17	32	26	74	9	21
ABF SSW 1/4	15 × 21	38	32	94	9	27
ABF SSW 1/5	20 × 27	50	42	110	12	34
ABF SSW 1/6	26 × 34	67	48	106	15	42
ABF SSW 1/7	33 × 42	67	56	121	15	49
ABF SSW 1/8	40 × 49	88	61	142	18	60

